

Fixed issues - FASTSUITE Edition 2 - R2024.2.4

#	Title
53389	ABB double angle wrist painting robot support
53587	X and Y support plates are not trimmed to edge of baseplate when using a large flange width
53632	Incorrect message when loading a controller "E2 has automatically upgraded some components while loading ..."
54176	Laserdyne trepanning issue
54242	Upload not working if downloaded program will be uploaded again (PRIMA)
53634	Engraving in nesting not shown
52438	Unexpected error with export of PSO data
52808	Unable to export the process simulation object data to a chinese folder
52920	Motion type in speed event is not correct in uploaded program
53604	Offset in teach after changing the limits of X-axis (PRIMA)
51287	Support plate curves intersect themselves
53883	Borrow expired maintenance license not working
53898	Upload G113/G114 does not work if no program exist (PRIMA)
53900	Upload not considering modality of X,Y,Z (PRIMA)
54016	RECT macro rotated 90 degrees after upload (PRIMA)
54022	CIRCLE macro showing visualization for lead-in (PRIMA)
54042	Upload not considering manually changed footer (PRIMA)
54108	Support if check parameter for macros (PRIMA)
54148	Upload : Copy/Paste with uploaded Program does not work
51594	Split support plate command causes plates to be overlapping on Y plates