

## Fixed issues - FASTSUITE Edition 2 - R2025.1.3

#	Title
56004	Flanges when using Length - "support plate with given length"
56190	Engraving and holes overlapping
56217	Collisions are not solved - Operation linking missing from active program therefore ALG not possible
57358	OTC - Welding Program 0 - error
57443	DynamicLimits not working with external plugin
57643	Toolchange / Swipe : Toolpath not created
57711	PG properties touch points issue
57733	Download not working - LaserZjStoreNumber
57835	Upload SinumerikOne: feedrate=10000 is too much in the uploaded program
57898	Onsite: Upload/Download Slot has different position
58059	Digital Twin: Transfer even though there are collisions
58124	Simulation stops while Portal > 90 (errorCode: 10338)
58384	Download / computation takes very long - bad performance