

## FASTSUITE R2025.2.2

ID	Work Item Type	Title
<a href="#">59889</a>	Feature	Support Recoule machine kinematic in OLP - Step 1
<a href="#">57216</a>	Feature	New cost function for point based APO/ALG
<a href="#">59021</a>	Feature	Default PTP Velocity for first toolpath element
<a href="#">60064</a>	Feature	APO,AARO,ALG support of technology Sealing
<a href="#">59084</a>	Feature	ArcWelding Standard Events for Surfacing (Durmat)
<a href="#">55855</a>	Bug	Regression (to R2024.2.5): Arc Welding Report does not work
<a href="#">60177</a>	Bug	FixtureBuilder : Add check if tower is intersecting a support plate and vice versa
<a href="#">59986</a>	Bug	Fixture Builder - Plate intersects workpiece
<a href="#">58363</a>	Bug	FixtureBuilder : Mirror Support plate Failure in Fixture Builder
<a href="#">60109</a>	Bug	Crash: Change Workpiece positioner axis
<a href="#">60200</a>	Bug	CRASH: Kernel exception after PG creation
<a href="#">59819</a>	Bug	Fanuc VNC connector does not work anymore for controller group 2 and 3
<a href="#">59334</a>	Bug	Chinese Folder Plugin issue
<a href="#">59820</a>	Bug	Not possible to delete AARO(only) optimization
<a href="#">55472</a>	Bug	Kinematics will get broken after editing joint parameters of the resource and reopen cenprj file
<a href="#">56270</a>	Bug	Low performance when open/close APD with ~ 1000 PGs programmed
<a href="#">60371</a>	Bug	Programming defaults - wrong toolpath quality icon
<a href="#">55524</a>	Bug	Regression (to R2022.2.6) - Load controller via Add existing objects after File new
<a href="#">60320</a>	Bug	Workpiece create, Name is empty (only in german environment)
<a href="#">56721</a>	Bug	PG Sort issue
<a href="#">60255</a>	Bug	Processmodel : API missing X-direction in the arguments of ComputeToolProcessModel()
<a href="#">60735</a>	User Story	Enhance the JTImportOption API to allow disabling the import of the ActiveLayer
<a href="#">60477</a>	Bug	[Regression] Crash after doing mirror of TP
<a href="#">60692</a>	Bug	Upload doesn't support Unit for BuildIn Events
<a href="#">58605</a>	Bug	Durmat: ArcWeldSurface: Defined welding speed is not used in ArcON line
<a href="#">59679</a>	Bug	Additional edit side tangent pie menu command added on each same file new / file reopen
<a href="#">60637</a>	Bug	"Downhand" not working when Tool alignment is set to x-axis
<a href="#">60514</a>	Bug	Kineo problems with app/ret ....runs more or less endless - Export problem
<a href="#">60523</a>	Bug	Lasercutting, Regshape, Reference Point Singularity management does not work
<a href="#">60592</a>	Bug	Kineo problems with app/ret - Follower of #60514 - asynchronous axis is exported and created in Kineo
<a href="#">60593</a>	Bug	Kineo problems with app/ret - Follower of #60514 - Freeflyer joint (for dynamic baseframe support) is wrong created in Kineo
<a href="#">60632</a>	Bug	Python function "AddEventSetBoolSignal(..) not working in current release
<a href="#">59902</a>	Bug	Regression (to R2024.2): Step through keyboard does not work after suppress and unsuppress
<a href="#">60133</a>	Bug	Partial Simulation Executes Previous Resource Port Events
<a href="#">60372</a>	Bug	APO FAILED: 5 axis laser contour pg
<a href="#">60405</a>	Bug	Drilling APO error message when loading cndoc with drilling technology





