



## Fixed issues - FASTSUITE Edition 2 - R2025.1.4

#	Title
59224	LeadIn point reset after recompute during SeamTracking
59237	RATC: PTP-Simulation with subprograms not working
53176	Cable simulation returns unexpected results
57401	Plugin Manager - DAIHEN
58588	Prima Upload: missing visualization of HOLE macro
58420	Regression: R2025.1.x crashing when connect to an OPC-UA server for its first time
58505	Cable hose doesn't work like expected
58517	Regression to R2022.2.3: Target position unreachable
58557	ArcWelding Python Extension - Attributes visibility
58558	Upload: A axis wrong if first A axis value is > 180 degree
58824	ArcWeld-ArcSpotWM: Multi-PG with No-Appr/Retr and ApprRetrOption failing
59338	There is no Incident list in Active program and Toolpath dashboard if there are only subprograms
57709	Teach insert in approach/retract is deleted after modification in previous operation and manual recomputation